

5.4 PHOTOGRAPH LOG



ORIGINAL
(Red)

Photo 1 -
Toluene spill area looking southwest.



Photo 2 -
Toluene spill area looking north.

5.4 PHOTOGRAPH LOG



ORIGINAL
(Red)

Photo 1 -
Toluene spill area looking southwest.



Photo 2 -
Toluene spill area looking north.



— Photo 3 -
— Toluene spill area and limestone gravel
— surface.



— Photo 4 -
— Toluene spill area and monitoring well.

BASF Wyandotte

F3-8412-17

WV-121

R1P4

Photo No 3

Toluene spill area, Limestone gravel surface.

2-4-85

Randall Dickinson

Randall Dickinson

Photo 3 -
Toluene spill area and limestone gravel
surface.

BASF Wyandotte

F3-8412-17

WV-121

R1P1

Photo No 4

Toluene Spill area. Monitoring well

2-4-85

Randall Dickinson

Randall Dickinson

Photo 4 -
Toluene spill area and monitoring well.



— Photo 5 - 31st Street Landfill. Floodwall
— side of landfill showing surface drainage
— ditch, looking south.



— Photo 6 - 31st Street Landfill
— Crest of landfill, looking south.
—

BASF Wyandotte

F3-8412-17

WV-121

R2 P2

Photo 4

5

RKD

2-5-85

31st Street Landfill

Floodwall side of landfill showing surface
drainage ditch. Looking south

2-4-85

Randall Dickinson

Randall Dickinson

Photo 5 - 31st Street Landfill. Floodwall
side of landfill showing surface drainage
ditch, looking south.

BASF Wyandotte

F3-8412-17

WV-121

R2 P3

Photo 6

6

RKD

2-5-85

31st Street Landfill

Crest of landfill. Looking south

2-4-85

Randall Dickinson

Randall Dickinson

Photo 6 - 31st Street Landfill
Crest of landfill, looking south.



— Photo 7 - 31st Street landfill —
 — Riverside of landfill, viewed from crest. —
 — Looking east. Note hay bales/ —



— Photo 8 - 31st Street Landfill. —
 — Monitoring wells, looking south. —

BASF Wyandotte

R2 P4

F3-8412-17

Photo 5

WV-121

7
RLO
2-5-85

31st Street Landfill

River side of landfill, viewed from crest.
Looking east. Note hay bales

2-4-85

Randall Dickinson

Randall Dickinson

Photo 5 - 31st Street Landfill
Riverside of landfill, viewed from crest.
Looking east. Note hay bales

BASF Wyandotte

R2 P6

F3-8412-17

Photo 4

WV-121

8
RLO
2-5-85

31st Street Landfill

Monitoring wells. Looking south

2-4-85

Randall Dickinson

Randall Dickinson

Photo 8 - 31st Street Landfill.
Monitoring wells, looking south.



— Photo 9 - 31st Street Landfill ORIGINAL —
 — River side of landfill, looking south. —
 —



— Photo 10 - 31st Street Landfill —
 — Seepage out onto Guyandotte River, —
 — looking east. —

BASF Wyandotte
F3-8412-17
WV-121

R2P7
Photo 5
9
RKD
2-5-85

31st Street Landfill

River side of landfill. Looking south

2-4-85

Randall Dickinson

Randall Dickinson

Photo 9 - 31st Street Landfill
River side of landfill. Looking south.

BASF Wyandotte
F3-8412-17
WV-121

R2P10
Photo 6
10
RKD
2-5-85

31st Street Landfill

Seepage out onto Guyandotte River. Looking east

2-4-85

Randall Dickinson

Randall Dickinson

Photo 10 - 31st Street Landfill
Seepage out onto Guyandotte River.
Looking east.